

## USB7002 Silicon Errata and Data Sheet Clarification

This document describes known silicon errata for the USB7002 devices. The silicon errata discussed in this document are for silicon revisions as listed in [Table 1](#). A summary of USB7002 silicon errata is provided in [Table 2](#).

**TABLE 1: AFFECTED SILICON REVISIONS**

Part Numbers	Silicon Revision
USB7002	B0

**TABLE 2: SILICON ISSUE SUMMARY**

Item Number	Silicon Issue Summary
1.	<a href="#">Ganged port power control mode limitations</a>
2.	<a href="#">Incompatibility issue with SST25 series SPI flash devices</a>
3.	<a href="#">Undefined SMBus OTP access commands execute an OTP read</a>
4.	<a href="#">Unsupported 'Set Interface' command does not issue a STALL response</a>
5.	<a href="#">Suspend Current Consumption delta between SPI FW execution and ROM FW execution</a>
6.	<a href="#">VCONN overcurrent loops infinite retries while in DCP mode</a>
7.	<a href="#">Invalid memory region access is not blocked</a>
8.	<a href="#">Force DCP feature overcurrent bug</a>
A.	<a href="#">Document Revision History</a>

### Silicon Errata Issues

#### Module 1: Ganged port power control mode limitations

##### DESCRIPTION

'Ganged mode' port power control is not recommended when using Type-C ports, as Type-C ports require individual VBUS enable controls to operate in a fully compliant way. The hub should only be configured for 'ganged mode' operation if all of the downstream ports are re-configured for legacy Type-A operation via the PORT\_CFG\_SEL register.

##### END USER IMPLICATIONS

None. Ganged port power control mode should not be used if any downstream ports are configured as Type-C ports.

##### Work around

none

##### PLAN

There is no plan to address this item.

# USB7002

---

## Module 2: Incompatibility issue with SST25 series SPI flash devices

### DESCRIPTION

The Hub ROM firmware fails to retrieve the JEDEC ID for SST25 series SPI Flash when hub has booted and is executing the firmware from the SPI Flash device. The resulting issue is that attempts to program the pseudo-OTP memory space within the SPI flash device will fail. It is possible to program the pseudo OTP when running from ROM

### END USER IMPLICATIONS

Updating the pseudo-OTP memory will not work in the standard way when running and external firmware image from an SST25 series SPI flash.

#### Work around

If running the firmware image from an external SST25 series SPI Flash device, and it is required to update the pseudo-OTP, the hub must be forced to reset and boot from internal ROM firmware image first. The pseudo OTP of the SPI Flash can then be updated while the hub is running from internal ROM firmware.

### PLAN

There is no plan to address this item.

## Module 3: Undefined SMBus OTP access commands execute an OTP read

### DESCRIPTION

The OTP Read via SMBus command is 0x07. Commands 0x0A - 0xFF are undefined commands, but operate as OTP Read if issued.

### END USER IMPLICATIONS

If undefined SMBus OTP commands 0x0A to 0xFF are issued, then an OTP Read will occur. This should have no negative impact on any applications.

### PLAN

There is no plan to address this item.

## Module 4: Unsupported 'Set Interface' command does not issue a STALL response

### DESCRIPTION

When configuring an unsupported firmware interface & alternate setting combination through a SET\_INTERFACE command from host to the hub's internal Hub Feature Controller device (UDC0), the Hub Feature Controller will not issue a STALL response.

### END USER IMPLICATIONS

None. The end user should never issue unsupported SET\_INTERFACE commands.

#### Work around

none

### PLAN

There is no plan to address this item.

## **Module 5: Suspend Current Consumption delta between SPI FW execution and ROM FW execution**

### DESCRIPTION

Suspend current of the hub is typically 16mA when running from internal ROM firmware, and 11.8mA when running from external SPI firmware.

### END USER IMPLICATIONS

While power consumption of the hub IC while in suspend is higher when running from internal ROM firmware image than with an external SPI firmware image, the total system power consumption may still lower when executing from internal ROM firmware image because this figure does not take into account the amount of power required to power a SPI Flash device.

#### **Work around**

none

### PLAN

There is no plan to address this item at this time.

## **Module 6: VCONN overcurrent loops infinite retries while in DCP mode**

### DESCRIPTION

When a USB port has battery charging enabled, and the port is in the DCP state (no USB host is present), a persistent fault on the VCONN supply will retry endlessly.

For comparison, if a persistent fault has been detected on VBUS while in the DCP state, the hub will latch off VBUS after several consecutive failed retries.

### END USER IMPLICATIONS

A consumer with a defective electronically marked cable may observe constant toggling of power to the attached device. This may result in rapid appearance and disappearance of a charging icon or indicator on an attached device.

#### **Work around**

Use the latest firmware version executed externally from a connected SPI Flash memory.

### PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

## **Module 7: Invalid memory region access is not blocked**

### DESCRIPTION

The hub firmware does not prevent access for the invalid memory region 0xBF90\_0000 - 0xBF90\_2FFF. Attempting to access this memory region will result in a firmware exception.

### END USER IMPLICATIONS

None. These memory addresses have no use, and should never be accessed in a normal application.

#### **Work around**

Use the latest firmware version executed externally from a connected SPI Flash memory.

### PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

## Module 8: Force DCP feature overcurrent bug

### DESCRIPTION

When using the “Force DCP” feature on a port by issuing the SET\_PORT\_DCP\_MODE vendor request, the hub memory read/write functionality will cease to work following an overcurrent event on the port.

### END USER IMPLICATIONS

The “Force DCP” feature if using the hub ROM firmware.

#### **Work around**

Use the latest firmware version executed externally from a connected SPI Flash memory.

### PLAN

This issue has been fixed in an updated firmware release. The latest firmware release may be loaded to an external SPI flash device and executed by the hub. There is no plan to update the hub ROM firmware image at this time.

## APPENDIX A: DOCUMENT REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS80000811A (11-26-18)	All	Initial release

# USB7002

---

## THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at [www.microchip.com](http://www.microchip.com). This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at [www.microchip.com](http://www.microchip.com). Under "Support", click on "Customer Change Notification" and follow the registration instructions.

## CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

**Technical support is available through the web site at: <http://microchip.com/support>**

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

**Trademarks**

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Helder, JukeBlox, KeeLoq, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntelliMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestlC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 9781522439103

---

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-67-3636

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820