

Notification Number:	20160901001	Notification Date:	Sept. 14, 2016
Title:	Datasheet update for TLV237x		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



TLV2370, TLV2371, TLV2372
TLV2373, TLV2374, TLV2375

SLOS270F –MARCH 2001–REVISED AUGUST 2016

Changes from Revision E (May 2016) to Revision F	Page
• Changed names of pins 2 and 3 in TLV2372 D, DGK, and P packages pinout diagram	4

The datasheet number will be changing.

Device Family	Change From:	Change To:
TLV237x	SLOS270E	SLOS270F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TLV2370>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TLV2370ID	TLV2371IDR	TLV2373IDG4	TLV2374IPW
TLV2370IDBVR	TLV2371IDRG4	TLV2373IDGS	TLV2374IPWG4
TLV2370IDBVRG4	TLV2371IP	TLV2373IDGSG4	TLV2374IPWR
TLV2370IDBVT	TLV2371IPE4	TLV2373IDGSR	TLV2374IPWRG4
TLV2370IDBVTG4	TLV2372ID	TLV2373IDGSRG4	TLV2375ID
TLV2370IDG4	TLV2372IDG4	TLV2373IDR	TLV2375IDG4
TLV2370IDR	TLV2372IDGK	TLV2373IDRG4	TLV2375IDR

TLV2370IP	TLV2372IDGKG4	TLV2373IN	TLV2375IDRG4
TLV2370IPE4	TLV2372IDGKR	TLV2374-W	TLV2375IN
TLV2371ID	TLV2372IDGKRG4	TLV2374ID	TLV2375IPW
TLV2371IDBVR	TLV2372IDR	TLV2374IDG4	TLV2375IPWG4
TLV2371IDBVRG4	TLV2372IDRG4	TLV2374IDR	TLV2375IPWR
TLV2371IDBVT	TLV2372IP	TLV2374IDRG4	TLV2375IPWRG4
TLV2371IDBVTG4	TLV2372IPE4	TLV2374IN	
TLV2371IDG4	TLV2373ID	TLV2374INE4	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com