

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Change of mold cavity affecting IAUA200N04S5N010, IAUA180N04S5N012, IAUA120N04S5N014 for PG-HSOF-5

INFORMATION NOTE



N° 051/19

Change of mold cavity affecting IAUA200N04S5N010, IAUA180N04S5N012, IAUA120N04S5N014 for PG-HSOF-5

► **Products affected:**

Please refer to attached affected product list 1_cip05119

► **Detailed Change Information:**

Subject: Relocate Mold Gate position


Reason: Process Improvement and assure of supply stability

Description: Old


New

Gate position

■ Gate on right



■ Shifted Gate on left side



► **Product Identification:**

Traceability assured via date code.
No change in SP ordering number

► **Impact of Change:**

POD will not change only mold gate position
Gate is visible on outside package

► **Attachments:**

Affected product list 1_cip05119

► **Intended start of delivery:**

20th September 2019

If you have any questions, please do not hesitate to contact your local Sales office.

IN 051/19

Change of mold cavity affecting IAUA200N04S5N010, IAUA180N04S5N012,
IAUA120N04S5N014 for PG-HSOF-5



Sales Name	SP number	OPN	Package
IAUA200N04S5N010	SP001497688	IAUA200N04S5N010AUMA1	PG-HSOF-5
IAUA180N04S5N012	SP002655470	IAUA180N04S5N012AUMA1	PG-HSOF-5
IAUA120N04S5N014	SP001497666	IAUA120N04S5N014AUMA1	PG-HSOF-5