

# INFORMATION NOTE

N° 073/15

**Introduction of a data matrix code (DMC) marking affecting dedicated devices.**

**Subject of Change:** Introduction of a data matrix code (DMC) marking affecting dedicated devices.

**Products affected:**

SalesName	SP	OPN	Package
TLE4921-5U	SP000013593	TLE49215UHALA1	PG-SSO-4-1
TLE4921M5U	SP000098770	TLE4921M5UHALA1	PG-SSO-4-1


**Reason of Change:** Data matrix code increases the internal traceability inside one lot.

**Description of Change:**

■ **Product Marking (Bottom):**


Old

Without DMC code on the backside of package:



New

Without DMC code on the backside of package:



*Or*

with DMC code on the back side of package:




# INFORMATION NOTE


N° 073/15

■ **Product Marking (Top):**

Without **DMC** code on the backside of package:




Without DMC code on the backside of package:



*Or*

**with** DMC code on the back side of package:



**Assessment:**

DMC already printed on similar products without any impact known. Only visual change on package backside but no further change on fit, form and function.

**Time Schedule:**

From December 2015 onwards.

**Documentation:**

n.a.

If you have any questions, please do not hesitate to contact your local Sales office.