



Final Product/Process Change Notification

Document #:FPCN23934X1

Issue Date:06 May 2022

Title of Change:	Update to FPCN23934X -To inform customers that define changes in the original FPCN (proposal additional Polyimide martial BL401 qualification at ASEKH) will no longer take effect	
Proposed First Ship date:	06 May 2022 or earlier if approved by customer	
Contact Information:	Contact your local onsemi Sales Office or Thomas.Chen@onsemi.com	
PCN Samples Contact:	Contact your local onsemi Sales Office. Sample requests are to be submitted no later than 30 days from the date of first notification, Initial PCN or Final PCN, for this change. Samples delivery timing will be subject to request date, sample quantity and special customer packing/label requirements.	
Additional Reliability Data:	Contact your local onsemi Sales Office or Rob.Travis@onsemi.com	
Type of Notification:	This is a Final Product/Process Change Notification (FPCN) sent to customers. FPCNs are issued 90 days prior to implementation of the change. onsemi will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact PCN.Support@onsemi.com .	
Marking of Parts/ Traceability of Change:	No change	
Change Category:	Assembly Change	
Change Sub-Category(s):	Material Change	
Sites Affected:		
onsemi Sites	External Foundry/Subcon Sites	
None	ASEKH, Taiwan (Kaohsiung)	
Description and Purpose:		
This update notification is to inform customers that define changes in the original FPCN (proposal additional Polyimide martial BL401 qualification at ASEKH) will no longer take effect, so as below. Polyimide martial still keep same as before change as HD4000E(HDM).		
	Before Change Description	After Change Description
Final Polyimide	HD4000E(HDM)	HD4000E(HDM)
There is no product marking change.		
Reliability Data Summary:		
Not applicable.		
Electrical Characteristics Summary:		
Electrical characteristics are not impacted.		
List of Affected Parts:		
<i>Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the PCN Customized Portal.</i>		
Part Number	Qualification Vehicle	
FAN53200UC44X	FAN53870UC00X	



Final Product/Process Change Notification

Document #:FPCN23934X1

Issue Date:06 May 2022

FAN53526UC00SX	FAN53870UC00X
FAN53526UC00X	FAN53870UC00X
FAN53526UC106X	FAN53870UC00X
FAN53526UC128X	FAN53870UC00X
FAN53526UC168X	FAN53870UC00X
FAN53526UC288X	FAN53870UC00X
FAN53526UC64X	FAN53870UC00X
FAN53526UC89X	FAN53870UC00X
FAN53555BUC79X	FAN53870UC00X
FAN53555UC04X	FAN53870UC00X
FAN53600AUC33X	FAN53870UC00X
FAN53610AUC33X	FAN53870UC00X
FAN53611AUC12X	FAN53870UC00X
FAN53611AUC18X	FAN53870UC00X
FAN5361UC182X	FAN53870UC00X
FAN53742UC00X	FAN53870UC00X
FAN53870UC00X	FAN53870UC00X
FPF1203LUCX	FAN53870UC00X
FPF1203UCX	FAN53870UC00X
FPF1320UCX	FAN53870UC00X
FPF1321BUCX	FAN53870UC00X
FPF1321UCX	FAN53870UC00X
FPF1504LUCX	FAN53870UC00X
FPF1504UCX	FAN53870UC00X
FPF2195	FAN53870UC00X
FPF2195UCX-SN00331	FAN53870UC00X
FPF2280BUCX-F130	FAN53870UC00X
FPF2281BUCX-F130	FAN53870UC00X
FPF2283CUCX	FAN53870UC00X
FPF2286UCX	FAN53870UC00X
FPF2495CUCX	FAN53870UC00X
FPF2495UCX	FAN53870UC00X
FPF2496UCX	FAN53870UC00X
FPF2595UCX	FAN53870UC00X



Final Product/Process Change Notification

Document #:FPCN23934X1

Issue Date:06 May 2022

FPF2895CUCX	FAN53870UC00X
FPF2895UCX	FAN53870UC00X
FPF3042UCX	FAN53870UC00X
FPF3188AUCX	FPF3788UCX
FPF3380UCX	FAN53870UC00X
SCY99231FCCT1G	FAN53870UC00X
SCY53713UC10X	FAN53870UC00X
FUSB302BUCX	FAN53870UC00X
FUSB251UCX	FAN53870UC00X
FTL75939UCX	FAN53870UC00X
FSUSB242UCX-Z002	FAN53870UC00X
FSUSB242UCX	FAN53870UC00X
FSA553UCX	FAN53870UC00X
FSA550UCX	FAN53870UC00X
FSA550BUCX	FAN53870UC00X
FAN53740UCA1X	FAN53870UC00X
FAN53526UC84X	FAN53870UC00X
FAN38522UCX	FAN53870UC00X
FAN48618BUC53X	FAN53870UC00X
FAN4861UC55X	FAN53870UC00X
FAN48623UC50GX	FAN53870UC00X
FAN48623UC50X	FAN53870UC00X
FAN48630BUC31JX	FAN53870UC00X
FAN48630UC315X	FAN53870UC00X
FAN48630UC33X	FAN53870UC00X
FAN48630UC50X	FAN53870UC00X
FAN48632UC33X	FAN53870UC00X
FAN48632UC35X	FAN53870UC00X
FAN49103AUC330X	FAN53870UC00X
FAN49103AUC340X	FAN53870UC00X
FAN49101AUC340X	FAN53870UC00X
FAN49100AUC360X	FAN53870UC00X
FAN49100AUC330X	FAN53870UC00X
FFG1040UC003X	FAN53870UC00X



Final Product/Process Change Notification
Document #:FPCN23934X1
Issue Date:06 May 2022

FAN54063UCX	FAN53870UC00X
-------------	---------------

Appendix A: Changed Products

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FAN53526UC00X		FAN53870UC00X	NA	
FAN53526UC89X		FAN53870UC00X	NA	
FAN53555UC04X		FAN53870UC00X	NA	
FAN53600AUC33X		FAN53870UC00X	NA	
FAN53610AUC33X		FAN53870UC00X	NA	
FAN53611AUC12X		FAN53870UC00X	NA	
FAN53611AUC18X		FAN53870UC00X	NA	
FAN5361UC182X		FAN53870UC00X	NA	
FAN53870UC00X		FAN53870UC00X	NA	
FPF1203LUCX		FAN53870UC00X	NA	
FPF1203UCX		FAN53870UC00X	NA	
FPF1321BUCX		FAN53870UC00X	NA	
FAN53526UC288X		FAN53870UC00X	NA	
FPF1320UCX		FAN53870UC00X	NA	
FPF1504LUCX		FAN53870UC00X	NA	
FPF1321UCX		FAN53870UC00X	NA	
FPF2195		FAN53870UC00X	NA	
FPF1504UCX		FAN53870UC00X	NA	
FPF2281BUCX-F130		FAN53870UC00X	NA	
FPF2280BUCX-F130		FAN53870UC00X	NA	
FPF2286UCX		FAN53870UC00X	NA	
FPF2283CUCX		FAN53870UC00X	NA	
FPF2495UCX		FAN53870UC00X	NA	
FPF2495CUCX		FAN53870UC00X	NA	
FPF2595UCX		FAN53870UC00X	NA	
FPF2496UCX		FAN53870UC00X	NA	
FPF2895UCX		FAN53870UC00X	NA	
FPF2895CUCX		FAN53870UC00X	NA	
FPF3380UCX		FAN53870UC00X	NA	
FPF3042UCX		FAN53870UC00X	NA	
FUSB251UCX		FAN53870UC00X	NA	
FUSB302BUCX		FAN53870UC00X	NA	
FSA550UCX		FAN53870UC00X	NA	
FSUSB242UCX		FAN53870UC00X	NA	
FSA553UCX		FAN53870UC00X	NA	
FSA550BUCX		FAN53870UC00X	NA	
FAN48623UC50GX		FAN53870UC00X	NA	
FAN53740UCA1X		FAN53870UC00X	NA	
FAN53526UC84X		FAN53870UC00X	NA	
FAN48623UC50X		FAN53870UC00X	NA	
FAN49103AUC340X		FAN53870UC00X	NA	
FAN48630UC50X		FAN53870UC00X	NA	
FFG1040UC003X		FAN53870UC00X	NA	
FAN48632UC33X		FAN53870UC00X	NA	
FAN49100AUC330X		FAN53870UC00X	NA	