

**PRODUCT CHANGE NOTIFICATION****PCN#** 2613**DATE:** 5/28/13**PRODUCT AFFECTED:****Product Number**

VSC7385XYV  
VSC7388XYU  
VSC7395XYV  
VSC7395XYV-03  
VSC7398XHJ-01  
VSC7398XYU  
VSC7398XYU-03  
VSC7401XHO  
VSC7405XHO  
VSC7407XHO  
VSC7407XHO-03

**CHARACTERISTIC AFFECTED:**

Product Discontinuance (EOL)

**PROPOSED CHANGES:**

For the products listed in this notification, the wafer foundry is discontinuing its wafer fabrication process. As a result, Vitesse is implementing a product discontinuation program for these devices to satisfy customer requirements.

For information about equivalent products in different packages that could be used in place of the discontinued parts, see the attached document.

**REASON FOR CHANGES:**

Vitesse's wafer facility is discontinuing its fabrication process for these parts.

**CUSTOMER RECOMMENDED ACTIONS:**

It is recommended that customers determine the remaining requirements for these products, and place final orders in accordance with the schedule that is included with this notification.

**PLANNED IMPLEMENTATION DATE:**

For information about the implementation plan, see the attached document.

**PLANNED EFFECTIVE DATE FOR CUSTOMER:**

For information about the effective date, see the attached document.

**SUMMARY OF SUPPORTING INFORMATION:**

The attached document contains additional information about this product discontinuance.