



ESSENTRA

COMPONENTS

February 1, 2021

To whom it may concern:

This is to inform you that Essentra has made the decision to obsolete the following part numbers. Our tooling for this part is not sufficient. There is no replacement part. This goes into effect immediately

Please let me know if you have any questions.

Best Regards,

Greg P. Mifsud
Director of Product Management

ESSENTRA COMPONENTS
3123 Station Road
Erie, PA 16510
United States of America

T (800) 899-9440
F (814) 899-2586
E saleserie@essentracomponents.com
www.essentracomponents.com

005150000005	005221000005	BTS145A	CTR110A	MSPT-11-01
005150059905	005221059905	BTS205A	CTWR001A	NWE-34815-M2.5
005150659914	005224000005	BTS210A	CTWR005A	NWE-34815-M5
005151200014	005224059905	BTS215A	DLSP-3-16M-01	OFBLTP-42-635V0
005151259905	005277059905	BTS220A	DLSP-3-18M-01	OFBUGB-0
005151259914	015004000503	BTS225A	EFA02-08-ASS	OFSH2-24-3
005151800005	224228	BTS230A	EFA04-08-001	OFSP-08-25
005151800014	284200022545	BTS235A	EFA04-18-001	OFSP-10-25
005151859905	495710	BTS240A	EFA04-34-R06	OFSP-10-30
005151859914	495711	BTS245A	EHCBS-6-10-01	OFSP-10-40
005152459914	495745	CCLA010A	EHCBS-6-14-01	OFSP-10-61
005153600005	495763	CCLA020A	EHCBS-8-5-19	PCBEHE2-12M-01
005153600014	495822	CCLA030A	EHCBS-8-6-19	PGSA-2024A1
005153659905	495825	CH-3-01	EHCBS-9-12-01	QM8
005153659914	495836	CH-3-01BK	EHCBS-9-14-01	RAD-20
005154800005	495896	CH-3-10	EHCBS-9-16-01	REHCBS-5-01
005154800014	495897	CH-3-10BK	EHCBS-9-8-01	RFRT-PN4
005154859905	495899	CMS-2BK	GCBS-3	RFRT-PN6
005154859914	495915	CTCS0150B	GR3401A	RKWS-8-12-BK
005156000005	495921	CTCS0520B	GRF33106A	RKWS-8-9-BK
005156000014	495933	CTCS0680B	GRF33109A	RLCBSK-2-14-01
005156059905	495960	CTCS1200B	GRF79815A	RS200B
005156059914	495962	CTCS1360B	HLCBSE2-14M-01	RS200W
005157800005	495967	CTCS1520B	HSM3-6.4-25-3	RS205W
005157800014	495968	CTCS1680B	LCBS-5-14-01	SCCA-4-19
005157859905	496004	CTCS1840B	LCBS-5-16-01	SCCB-2-19
005157859914	496012	CTLC0150B	LCBSTF-M4-16-01	SCCB-4-19
005159600005	496035	CTLC0225B	LCCBS-TM- 6-01	SCCB-6-19
005159600014	496040	CTLC0300B	LCCBS-TM- 8-01	SHK-12-01
005159659905	496041	CTLC0450B	LEDM-1-07	SHSM10L30A

005159659914	496042	CTLC0610B	LEDM-1-19	SHSM10L60A
005160800005	496090	CTLC1150B	LEDM-1-30	SHSM6L10A
005160800014	AS-1	CTLC1225B	LEDM-2-18	SHSM6L16A
005160859905	BHDF-10M-01	CTLC1300B	LEDM-2-29	SHSM6L25A
005160859914	BHEHCBS- 5-01	CTLC1450B	LEDM-2-30	SHSM8L10A
005163800005	BPM-1	CTLC1610B	LEDM-3-14	SHSM8L16A
005163800014	BTS005A	CTLS0150B	LEDM-3-24	SHSM8L25A
005163859905	BTS010A	CTLS0225B	LEDS1E-16-01	STL-1-350-20-01
005163859914	BTS015A	CTLS0450B	LLF-2	STL-1-750-20-01
005166800005	BTS020A	CTLS0610B	LLF-3	STL-2-250-16-01
005166800014	BTS025A	CTLS1150B	MDLSPK1-20M-01	STL-2-250-3-01
005166859914	BTS030A	CTLS1225B	ML-L-1	STL-2-350-3-01
005200000005	BTS035A	CTLS1300B	MSCBS- 4-19	STL-3-350-12-01
005200059905	BTS040A	CTLS1450B	MSCBS- 6-19	STL-3-450-12-01
005203000005	BTS045A	CTLS1610B	MSCBS- 8-19	STL-5-750-20-01
005203059905	BTS105A	CTR004A	MSCBSM-M4-9-01	STL-6-250-20-01
005206059905	BTS110A	CTR007A	MSCEHCBS- 4-01	STL-6-350-12-01
005209059905	BTS115A	CTR008A	MSCEHCBS- 6-01	STL-6-350-20-01
005212000005	BTS120A	CTR010A	MSPT- 4-01	STL-6-350-8-01
005212059905	BTS125A	CTR102A	MSPT- 5-01	STL-6-450-3-01
005215059905	BTS130A	CTR104A	MSPT- 6-01	STL-6-600-3-01
005218000005	BTS135A	CTR106A	MSPT- 7-01	STL-6-600-8-01
005218059905	BTS140A	CTR108A	MSPT- 8-01	STL-J-250-6M-01

TCS-2

TEHCBS-8-8-19

TFG95HA

TPCE5-51-8M-01

WIT-225L-L

WIT-225R-L

WITLP-50R-M

WITLP-50R-UVB-M

WSLT-9-02-1-01