



## Product Change Notification / SYST-12VRSN725

---

### Date:

13-Apr-2022

### Product Category:

Memory

### PCN Type:

Document Change

### Notification Subject:

Data Sheet - 34AA02/34LC02 2K I2C Serial EEPROM Software Write-Protect Data Sheet

### Affected CPNs:

[SYST-12VRSN725\\_Affected\\_CPN\\_04132022.pdf](#)

[SYST-12VRSN725\\_Affected\\_CPN\\_04132022.csv](#)

### Notification Text:

SYST-12VRSN725

Microchip has released a new Product Documents for the 34AA02/34LC02 2K I2C Serial EEPROM Software Write-Protect Data Sheet of devices. If you are using one of these devices please read the document located at [34AA02/34LC02 2K I2C Serial EEPROM Software Write-Protect Data Sheet](#).

**Notification Status:** Final

**Description of Change:** 1) Added Automotive Product Identification System section 2) Fixed TBUF typo and added 1 MHz spec 3) Updated MSOP, PDIP, SOIC, SOT-23, TDFN and TSSOP package drawings 4) Replaced terminology "Master" and "Slave" with "Host" and "Client", respectively 5) Reformatted some sections for better readability.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 13 Apr 2022

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

[34AA02/34LC02 2K I2C Serial EEPROM Software Write-Protect Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

34AA02-E/MS  
34AA02-E/P  
34AA02-E/SN  
34AA02-E/ST  
34AA02-I/MS  
34AA02-I/P  
34AA02-I/SN  
34AA02-I/ST  
34AA02T-E/MNY  
34AA02T-E/MS  
34AA02T-E/OT  
34AA02T-E/OT16KV02  
34AA02T-E/SN  
34AA02T-E/ST  
34AA02T-I/MNY  
34AA02T-I/MNYB21  
34AA02T-I/MNYB22  
34AA02T-I/MS  
34AA02T-I/OT  
34AA02T-I/SN  
34AA02T-I/ST  
34LC02-E/MS  
34LC02-E/P  
34LC02-E/SN  
34LC02-E/ST  
34LC02-I/MS  
34LC02-I/P  
34LC02-I/SN  
34LC02-I/ST  
34LC02T-E/MNY  
34LC02T-E/MNY16KV01  
34LC02T-E/MS  
34LC02T-E/OT  
34LC02T-E/SN  
34LC02T-E/ST  
34LC02T-I/MNY  
34LC02T-I/MNY16KVAO  
34LC02T-I/MS  
34LC02T-I/OT  
34LC02T-I/SN  
34LC02T-I/ST