



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000845

DATE: 25-Nov-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	806-0727-20+T	N/A			Part reactivated from prior notice: M000844
Reactivation	MAXQ2000-RAX+	N/A			Part reactivated from prior notice: M000844
Reactivation	MAXQ2000-RBX+	N/A			Part reactivated from prior notice: M000844
Reactivation	MXB7843EEE+	N/A			Part reactivated from prior notice: M000810
Lead-Free Conversion	DG442DY	DG442DY+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2250-32-16	DS2250-32-16+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2250T-32-16	DS2250T-32-16+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2250T-64-16	DS2250T-64-16+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS80C310-QCG	DS80C310-QCG+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS87C530-QNL	DS87C530-QNL+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS89C430-QNL	DS89C430-QNL+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1607ESA	MAX1607ESA+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1694EUB	MAX1694EUB+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1719EUT	MAX1719EUT+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1735EUK25	MAX1735EUK25+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1742EEE	MAX1742EEE+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1759EUB	MAX1759EUB+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1857EUA47	MAX1857EUA47+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1898EUB41	MAX1898EUB41+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX303MSE/PR	MAX303MSE/PR+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX4533EAP	MAX4533EAP+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX786CAI	MAX786CAI+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8875EUK33-T	MAX8875EUK33+T	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8878EUK25	MAX8878EUK25+	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS1220Y-100+	DS1220AD-100+	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1220Y-120+	DS1220AD-100+	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Dec-2016

Discontinuance	DS1220Y-150+	DS1220AD-100IND+	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1220Y-200+	DS1220AD-100+	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1220Y-200IND+	DS1220AD-100IND+	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1393U-18+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS21Q352	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS21Q354BN	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS2431P+W	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS2431X-S+TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS2432X-S+TW	DS28E22Q+T	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS2433AX-S+TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS2502X1+UW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28E07+W	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28E10P-W22+2TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28E15X+UW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28EL15Q-742+3TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28EL15Q-742+4TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28EL15Q-742+5TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS28EL15Q-742+6TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	DS3112N+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4160D+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4160P+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+100/100	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+100/150	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+125/125	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+125/156	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+150/150	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+150/200	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	DSQ3301-K04+TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MAX13085EASA+	MAX13085EESA+	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX13085EASA+T	MAX13085EESA+T	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX13170ECAI+	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX13170ECAI+T	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX13172ECAI+	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX13172ECAI+T	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX13174ECAG+	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX13174ECAG+T	N/A	25-Nov-2017	25-Nov-2018	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Dec-2016

Discontinuance	MAX15153ATJ+	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX1558EVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX16501M1EVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX16501V1EVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX1662EUB+	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX1662EUB+T	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX1662EVKIT	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX1668EVSYS	MAX1668EVKIT	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX16932BATIS/V+T	MAX16932CATIS/V+T	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX16986RATI/V+	N/A	25-Nov-2017	25-Nov-2018	The part was not released
Discontinuance	MAX17067EUA+T	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX17116EVC+	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX17116EVC+T	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX17116EVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX17116QEVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX1773EUP	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX20731EPL+S	MAX20731EPL+T	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MAX20732EPL+S	MAX20732EPL+T	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MAX20751ILBEVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX20751ILCEVKIT#	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2117EVKIT+	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2206EVKIT	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2209AEVKIT+	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2209EVKIT+	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2240EVKIT	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2242EVKIT	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX225CWI+G36	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX225CWI+TG36	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX225EWI+G36	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX32600-P85B+W	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MAX34451ETN+T	MAX34451ETNA1+T	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX5074AUP+	MAX5074AAUP+	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6972EVKIT	N/A	25-Nov-2016	25-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX72018C+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72024C+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72038B+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured

Discontinuance	MAX72044B+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72463B+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72466B#W	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX72466B+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72950#W	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX72950+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX72951+	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306ALB+	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306ALB+T	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306AUB+	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306AUB+T	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX8795AGCJ/V+GB	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9124EUE+	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	MAXQ617V-L000+TW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MAXQ617V-L000+UW	N/A	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	MXL1013DS8+T	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VSC410XKM	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VSC452XHW-05	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7153XSS-02	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7154XYS/C	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VSC7155VU-02	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7155XVU-02	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7156XYT-03	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7157XYS-03	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7157YS-03	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7158HT-03	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7158XHT-03	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VSC7170XYQ-01	N/A	25-Nov-2017	25-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	VT1323SFCX	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1324SFCX	N/A	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1326SFCR	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT1326SFCX	N/A	25-Nov-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT1546MBFQR	VT1546MBFQX	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1636SFQ	N/A	25-Jan-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT1636SFQX	N/A	25-Jan-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT235AWFQR-ADJ	VT235AWFQX-ADJ	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Dec-2016

Discontinuance	VT235WFQR-ADJ	VT235WFQX-ADJ	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT262AWFQR-ADJ	VT262AWFQX-ADJ	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT370FCR-ADJ	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT387FCX-ADJ	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT388FCR-ADJ	N/A	27-May-2017	25-Nov-2018	Part can no longer be manufactured
Discontinuance	VT503FQ	MAX16543GPC+	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	VT503FQX	MAX16543GPC+T	25-Nov-2016	25-Nov-2016	The part was not released
Discontinuance	VT505FQR	VT505FQX	25-Nov-2016	25-Nov-2016	Part can no longer be manufactured
Discontinuance	VT511FQ	MAX16551GPN+T	25-Nov-2016	25-Nov-2016	The part was not released