

Discontinuation: P5KS Series (Mated height: 4.0mm & 4.5mm) 120 & 160 pin contacts & Mated height: 6.5mm 130 pin contacts.

PEWA Ref # ACBD257

1.17.2014

| | |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Effective Date: | September 30, 2014 |
| Last Time Buy Date: | September 30, 2014 |
| Last Time Ship Date: | N/A |
| Discontinuation Details: | Decreasing market demand. |
| Suggested Replacement: | None |
| Affected Part Numbers: | AXK5SA2XX (Socket) 120 & 160 pin counts (4.0mm) AXK6SA2XX (Header) 120 & 160 pin counts (4.0mm) AXK5SA3XX (Socket) 120 & 160 pin counts (4.5mm) AXK6SA3XX (Header) 120 & 160 pin counts (4.5mm) AXK5SA6XX (Socket) 130pin count (Mated height 6.5mm) AXK6SA6XX (Header) 130pin count (Mated height 6.5mm) |
| Datasheets: | See attached. |
| Notes: | See attached discontinued part number list. |

Panasonic P5KS Series Discontinued Part Number List

Discontinued Part Number **Suggested Replacement Part Number**

Part # **Replacement Part #**

| | |
|--------------|----------------|
| AXK5SA2077YG | No replacement |
| AXK5SA2087YG | No replacement |
| AXK5SA2277YG | No replacement |
| AXK5SA2287YG | No replacement |
| AXK5SA3277YG | No replacement |
| AXK5SA3287YG | No replacement |
| AXK5SA6077YG | No replacement |
| AXK5SA6087YG | No replacement |
| AXK5SA6287YG | No replacement |
| AXK5SA6277YG | No replacement |